Solicitation W56HZV-16-R-0148

Question & Answer log

- (Q1) Item 3.1.1.36.2: Why does drawing number 11B4540038 (First Aid Kit) have the word CANCELLED written on the drawing? Are we to procure this item?
- (A1)Drawing 11B4540038 has been removed from the Technical Data Package (TDP). This item is now described by NSN 6545-01-433-8399 in the Bill of Material (BOM). This item is to be included in the tool load.
- (Q2)Item 3.1.1.1.10.3.14: this item (3/8") 12pt combo wrench) appears to be the same exact item as the item just before it? Was this a typo? Why not just ask for a quantity of 2?
- (A2) Yes, there was a typo. BOM has been revised to reflect the following:
- 3.1.1.1.10.3.13 11b4540055-6 Wrench, Combination, 12 pt, 7/16"
- 3.1.1.1.10.3.14 11b4540055-7 Wrench, Combination, 12 pt, 3/8"
- (Q3)3.1.1.1.10.7.3: Why does drawing number 11B4540091 (earplugs 200ct) have the word CANCELLED written on the drawing? Are we to procure this item?
- (A3)Drawing 11B4540091 has been removed from the Technical Data Package (TDP). This item is now described by NSN 6515-00-137-6345 in the Bill of Material (BOM). This item is to be included in the tool load.
- (Q4)3.1.1.17: Why does drawing number 11B45400112 (30lbs intermediate cylinder) have the word CANCELLED written on the drawing? Are we to procure this item?
- (A4) Item 3.1.1.17 has been removed from the BOM and TDP. This item is not required in the tool load.
- (Q5)Items 3.1.1.42 thru 3.1.1.45 appear on attachment 0004 but there are no drawings for these items in the TDP, are we to procure these items?
- (A5) Drawing 11B4510018, 11B4540033 and 11B4540079 have been added to the TDP as shown in the BOM for these respective items. These items are required in the tool load.

- (Q6)Items 3.1.1.1.11 and 3.1.1.43 (18k Air Conditioner and Cable assembly) both have National Stock Numbers (NSN) as shown in attachment 0004 but no accompanying TDP drawing for either item? Are these two items going to be Government Furnished items? Are we to procure these items?
- (A6) These items are not required in the tool load and have been removed from the BOM.
- (Q7)On attachment 0004 line item's 272 thru 299 beginning with Item number 3.1.1.23 and ending with 3.1.1.25.1 all have part numbers but no corresponding drawing in the TDP. Are we to procure these items?
- (A7) Yes, these items are required in the tool load. The part numbers correspond to the applicable standard or specification shown for each respective item.

Added from here 22DEC2016

- (Q8) Item 16: 06A8178001 mentions 06A8176302 (note 2) specs/ drawing is missing.
- (A8) Drawing 06A8176302 added to TDP dated 22DEC2016.
- (Q9) Items 18 and 19 mentions 06A8176202 (note 2) specs/drawing is missing.
- (A9)Drawing 06A8176202 added to TDP dated 22DEC2016.
- (Q10) Items 20-23 06A8176103 (note 2) specs/drawing is missing.
- (A10)Drawing 06A8176103 added to TDP dated 22DEC2016.
- (Q11) Also, I would like to get a drawing for ANTISLIP MAT 11B4541011 referred to in drawings 11B4541012 (item 259) and 11B4541013 (item 259).
- (A11)Drawing 11B4541011 added to TDP dated 22DEC2016.